





A (x2)




B (x2)



C (x2)




H (x1)
M8x65



D (x1)



E (x1)



F (x1)



G (x1)



I (x2)
M8x20



J (x2)
M6x10



K (x1)
4mm



L (x1)
5mm



M-A (x4)
M4x12









M-B (x4)
M5x12






M-C (x4)
D5




x2

1







2



3



4

